

WORKPLACE SAFETY NOTICE (WSN)

1 10916			Reference Number 2022/WSN/01
Approved by:	Issue date:	Expiry date:	Revision No:
Chief Inspector	1 March 2022	None	O

On 12th January 2022, a worker was pinned between the battery steel frame cover and the angle iron guard rail underneath the dumper bucket of a Dump Truck while he was trying to fix the truck battery. The worker died at the scene.



How can this accident be prevented?

Such accidents can be prevented when the following safety precautions are observed and applied at the workplace:

- a) Always ensure that the raised dumper bucket is adequately supported prior to working under it.
- b) Do not rely on the truck's hydraulic system to hold the dumper bucket up while working under it.

2022/WSN/01 Rev 0

- c) **Engage** the dumper-bucket lock bars before performing tasks under a raised dumper-bucket to ensure support is permanently attached and to prevent accidental lowering or sudden drop of the dumper-bucket body. 'Homemade' arrangements are **not advised** as means of support.
- d) Ensure dumper bucket remained fully lowered at all times.
- e) **Ensure** the Dump Truck and its mechanisms are **inspected** by a **competent person** and **maintained** regularly. All records of inspections and maintenance are to be kept for future reference.
- f) If there are any doubt on the operation of the Dump Truck, please **consult** the Operator's Manual of the Dump Truck or **contact** the Original Equipment Manufacturer.
- g) Before starting any work activity, please **perform a risk assessment** to identify all potential hazards and, if it is identified, to eliminate or control the hazard immediately.
- h) Avoid or minimise Lone Working.

SHENA seeks assistance from the public to ensure these precautions are extended to the relevant parties involved in the operation of Dump Trucks.

2022/WSN/01 Rev 0 2